No. 20, Jui-Kuan 2  $^{\rm nd}$  St., Ta-Fa Ind. Dist., Kaohsiung , Taiwan

TEL:886-7-787-7690

FAX:886-7-787-8456/0942 E-mail:top@pstop.com.tw web site:www.pstop.com.tw

Info. No. 112-1

PROBLEM	CAUSES	SUGGESTIONS & SOLUTIONS
Scumming: Non image areas become ink smuaged	(1) Glass of exposure machine or film are not clean.	(1) Cleaning the glass or film thoroughly with glass/film cleaner.
	<ul><li>(2) Glue marks for films montage not removed.</li><li>(3) Too much anti-forming liquid in the developer.</li></ul>	<ul> <li>(2) Choosing better tapes for composed images / films.</li> <li>(3) Make sure maximum 2 cc anti-foring liquid to be applied per 10 liters developer.</li> <li>Pay attention to the composition of developer used and be sure to mix them well.</li> </ul>
	<ul><li>(4) Foam of developer stayed on the plate and it affected the development.</li><li>(5) Plates are touched by unclean fingers (finger prints).</li><li>(6) The developer became weaker.</li></ul>	<ul> <li>(4) Some spray heads of developing machine can be stocked. Stop the processor and clean the spray head.</li> <li>(5) Holding the clamping part of plate only.</li> <li>(6) Standard applying capacity of developer is 26 sqm/l.</li> </ul>
	<ul> <li>(7) Insufficient density remained in gum solution.</li> <li>(8) Part of gum on plates are detached.(plates are stacked one by one).</li> <li>(9) Plates are stored in a high-temperature and/or humidity after development.</li> </ul>	<ul><li>(7) Dilute the gum solution according to the dilution ratio.</li><li>(8) After gumming, dry the plate and place the plate in an upright way.</li><li>(9) Put plates in a place without high temperature and humidity.</li></ul>
Spots after printing:	(1) Plate become oxidized.	(1) After printing, plates need to be gummed immediately. Use fountain solution containing "wetting agent". Please make sure arabic gum contained in the fountain solution is sufficient.

No. 20, Jui-Kuan 2 nd St., Ta-Fa Ind. Dist., Kaohsiung, Taiwan

TEL:886-7-787-7690

FAX:886-7-787-8456/0942  $E\hbox{-mail:top@pstop.com.tw} \quad web \ site: www.pstop.com.tw$ 

Info. No. 112-2

PROBLEM	CAUSES	SUGGESTIONS & SOLUTIONS
Scratching: marks or cuts on plate surface	(1) Insufficient density remained in gum solution.	(1) Make sure enough concentration and reliable gum solution to be applied.
Spots after plate baking:	(1) Baking gum solution applied unevenly.	(1) Applying baking gum solution on plates thoroughly and evenly.
	<ul><li>(1) Dirty on the glass of exposure machine.</li><li>(2) Spotted film.</li></ul>	<ul><li>(1) Use glass cleaner to clean the glass of exposure machine.</li><li>(2) Use film cleaner to clean the film.</li></ul>
·	(3) Non-smooth film composition.	(3) Keep the distance at least 3mm from the montage edge to the subject text.
Dot shrinkage	(4) Improper or shortage vacuum.	(4) Start exposing until full contact of PS plate and film is reached
	(5) Improper bottom paper or robber under exposure machine.	(5) Replace the bottom or robber periodically (make sure of flatness).
	(6) Insufficient density of film.	(6) Check the exposure value of film & its developer status.
	(7) Too strong developer applied.	(7) Check by gray scale.
	(8) Un-even light or aged lamp of exposure machine.	(8) Check & re-new the lamp while the certain time.
Stain (background of		
PS plate)	(1) Film was not transparent enough.	(1) Re-new the film.
	(2) Insufficient exposure time.	<ul><li>(2) a. Exposure as per the standard.</li><li>b. Proof printing: 2-3 steps clear.</li><li>c. Normal printing: 3-4 steps clear.</li><li>(UGRA scale 1982)</li></ul>
	(3) Aged lamp.	(3) Re-measure the standard time by gray scale.

No. 20, Jui-Kuan 2  $^{\rm nd}$  St., Ta-Fa Ind. Dist., Kaohsiung , Taiwan

TEL:886-7-787-7690

FAX:886-7-787-8456/0942

E-mail:top@pstop.com.tw web site:www.pstop.com.tw

Info. No. 112-3

PROBLEM	CAUSES	SUGGEST	TONS & SOI	LUTIONS
Stain (background of	※Insufficient Development	Developing a	s the following	g conditions:
PS plate)	(1) Developing temperature is too low.	Type	European-Type	Asian-Type
	(2) Too less developing time.	Temperature	25±2 ℃	25±2 ℃
	(3) Concentration of developer is insufficient.	Developer	Tp-4	Tp-4
	(4) Developer became weaker or un-workable.	Ratio (mixing with water)	1:5 / 1:6	1:7 / 1:8
	(5) Re-fill of developer improperly.	Developer refilling ratio	1:3	1:4
Stain when printing	<ol> <li>(1) Incorrect roller adjustment.</li> <li>(2) Too few alcohol quantity contained in fountain solution.</li> <li>(3) Dampener is dirty.</li> <li>(4) Incorrect PH value.</li> </ol>	<ul> <li>(2) 5%~15% stain.</li> <li>(3) Wash distinction isoproparate fountain those step Arabic gu</li> <li>(4) Normally</li> </ul>	r operation materious isopropanol to tributing roller alcohol; roller by consolution or cless, spread a layum. The PH value st by printing	o avoid  by  wash centrated caner; after yer of  is 5.5 ± 0.5
	<ul><li>(5) Printing plate stain on plate rollers.</li><li>(6) Ink problem.</li></ul>		proper water	
	(7) Water problem.	(7) Notice pu	rity of water, emulsification,	
	(8) High temperature and humidity.	1	the plate surfa ed.	ice will be

E-mail:top@pstop.com.tw

web site:www.pstop.com.tw

Info. No. 112-4

PROBLEM	CAUSES	SUGGESTIONS & SOLUTIONS
Poor ink adhesion	(1) Did not use designate gum solution.	(1) Pay attention to the quality of gum solution.
	(2) Concentration of gum solution is too high.	(2) Follow accurate gum solution dilute ratio.
	(3) Application of gum solution is unbalanced.	(3) After applying gum solution, wipe evenly by dry cloth.
	(4) Drying temperature is too high.	(4) Make sure drying temperature is below 60°C.
	(5) Print after plate's been processed for at least one week.	(5) If the plate will be used after the plate has been exposed for one week or longer, it is necessary to re-apply gum solution.
	(6) After applying gum solution, the plate has been irradiated by strong light.	(6) Avoid strong light irradiation after gum solution is applied.
	(7) Store the plate under hot and humid circumstance after exposure.	(7) Always store plates under moderate temperature and humidity.
	(8) Influenced from plate cleaner.	(8) Rinse the plate with water after applying cleaner, then use acid pickle to retouch it.
	(9) Developer fatigue.	(9) Standard applying capacity of developer is 26 sqm/L.



No. 20, Jui-Kuan 2nd St., Ta-Fa Ind. Dist., Kaohsiung, Taiwan

TEL:886-7-787-7690

FAX:886-7-787-8456/0942 E-mail:top@pstop.com.tw web site:www.pstop.com.tw

Info. No. 112-5

PROBLEM	CAUSES	SUGGESTIONS & SOLUTIONS
Run length impression	(1) Plate has been sensitized (before exposure, before development).	(1) Use yellow light in working area. Other pernicious lights must be eliminated. Pay attention to ultraviolet rays.
	(2) The black density tone of image on the film is insufficient.	(2) Remake the film. (density 3.5)
	(3) Over-exposure.	(3) Develop under standard instructions.
	(4) Developing temperature is too high.	(4) 25°C~27°C is most suitable.
	(5) Developing time is too long.	(5) Adjust time and speed.
	(6) Developer concentration is too high, or supply too much.	(6) 1:7~1:8.
	(7) Other chemicals are adhered on the plate, such as strong acid, alkali, organic solvent, and image remover, etc.	(7) Avoid using unsuitable chemicals.
	(8) Plate cleaner is too strong.	(8) Beware of the chemical erosion.
	(9) Acidity and alkalinity in fountain solution.	(9) PH5.5 $\pm$ 0.5 is the most suitable.
	(10) High printing pressure.	(10) Suitable printing pressure.
	(11) Paper structure, PH value.	(11) Friction coefficient is different with different paper.
	(12) Blanket characteristics, glazing cleaner.	(12) Use suitable blanket and beware of the chemical erosion.
	(13) Fountain solution's alcohol content.	(13) High alcohol content erode plates.
	(14) Ink related problem.	(14) Pay attention to ink characteristics.

No. 20, Jui-Kuan 2 nd St., Ta-Fa Ind. Dist., Kaohsiung, Taiwan

TEL:886-7-787-7690

FAX:886-7-787-8456/0942

E-mail:top@pstop.com.tw web site:www.pstop.com.tw

Info. No. 112-6

PROBLEM	CAUSES	SUGGESTIONS & SOLUTIONS	
Poor tone-grade	(1) Too much exposure.	(1) Exposure by correct time.  Sample printing with gray scale 2-3 steps clear. Printing with 3-4 steps clear, the 10th step must be all black.	
Plate correction	<ul> <li>※Insufficient correction</li> <li>(1) Insufficient plate corrector.</li> <li>(2) Plate left with too much water while doing plate correction.</li> <li>(3) Insufficient time for plate correction.</li> <li>(4) Plate corrector inaction. <ul> <li>(Lid is not properly sealed after use).</li> </ul> </li> <li>(5) Long plate correction time leads to the damage of hydrophile.</li> </ul>	<ol> <li>(1) Make sure adequate plate corrector is applied.</li> <li>(2) Make sure water is properly removed before plate correction.</li> <li>(3) Before washing the plate, allow at least 30-40 seconds time after plate corrector is applied.</li> <li>(4) Securely seal the lid after use.</li> <li>(5) Plate correction time should be carefully controlled within 30-40 seconds.</li> </ol>	
Stain on the rim of corrected area	(1) Insufficient exposure.  (2) Insufficient development (The remnants of correctors amass at the rim of the part where corrected.	(1) Exposure based on the correct exposure time. (2) Develop based on the correct development time.	
Dot lost on the rim of corrected area	<ul><li>(1) Plate corrector spreads to the figures.</li><li>(2) Influenced by the gaseous matter.</li></ul>	<ul><li>(1) Make sure water is properly removed before plate correction.</li><li>(2) Use mild dot corrector. Correct the plate after glue is applied.</li></ul>	

No. 20, Jui-Kuan 2<sup>nd</sup> St., Ta-Fa Ind. Dist., Kaohsiung, Taiwan

TEL:886-7-787-7690

FAX:886-7-787-8456/0942

E-mail:top@pstop.com.tw web site:www.pstop.com.tw

Info. No. 112-7

## TROUBLESHOOTING OF PS PLATES

#### Use of gray scale:

To increase each one clear step, increase 1.4 times of current exposure time.

To decrease each one clear step, expose the plate at 0.7 times of current exposure time.

#### Insufficient exposure time will lead to:

- 1. Plate hydrophile will get stain after press printing.
- 2. Fail to delete the tape shade of the original film and take more time for the correction.

#### Excessive exposure time will lead to:

- 1. Printing line becomes slim, dot losing and poor reproduction of dot line.
- 2. Poor ink ability for the printing line.

The printing run for positive PS plate will not be influenced by various exposure times. However, if the black density is not sufficient on the flim, the printing line will lead to partial exposed so that after plate processing, printing run will be shortened.

